



Material Safety Data Sheet / *americancrete* Terrazzo Floor

Component of the formulated polyurethane system for
americancrete Terrazzo

Hazard Identification

Designation: Xn - Harmful

Information: R20 - Harmful by inhalation

R36/37/38 - Irritation to eyes, respiratory system and skin

R42 - May cause sensitization by inhalation

General Notes: Product is a respiratory irritant and potential respiratory sensitizes. Repeated inhalation of vapour or aerosol at levels above the occupational exposure limit could cause respiratory sensitization.

Safety Precautions

Avoid skin and eye contact. Wear goggles/visor, impervious-gloves and protective clothing. Ensure area is well ventilated or use respiratory protection.

Environmental Precautions: Remove sources of ignition. Do not allow Product to reach sewage system or any water-course. Prevent seepage into workpits and cellars. Inform respective authorities in case of seepage into water course or sewage system.

First Aid Measures

General: Remove soiled clothing immediately. In case of accident or if you feel unwell, seek medical advice immediately (show label where possible).

After inhalation: Move victim to fresh air, keep warm and allow to rest. Obtain medical attention.

After skin contact: Remove contaminated clothing. Wash immediately with plenty of soap and water. In case of persistent irritation/rash, seek medical attention.

After eye contact: Rinse immediately with plenty of water. Continue for 15 minutes and seek medical attention.

After swallowing: provided patient is conscious, rinse mouth with water and give half a pint of water to drink. Do not induce vomiting. Obtain immediate medical attention.

Fire Fighting Measures

In case of fire, use powder, foam, carbon dioxide. Do not use water jet. Toxic gases and vapours are produced in a fire.

Clean up Procedure

Absorb spillages with sand, earth or any suitable non-combustible absorbent material. A suitable decontaminant is as follows:

- Water 90%
- Concentrated ammonia solution 8%
- Liquid detergent 2%

Handling and Storage

Handling: Ensure good ventilation. Avoid contact with skin and eyes. Atmospheric concentrations should be minimized and kept as low as practicable below the occupational exposure limit.

Storage: Keep containers properly sealed and store indoors in a well ventilated area. Avoid any contact with moisture. Store in a cool location. Avoid copper, copper alloy and galvanized surfaces.

October 1, 2009

Website: www.americancrete.com